


Timpani Condition Report

Instrument: Pedal Timpani
 Make: Adams
 Model: Big Sound




Head, Hoops & Rings
 The heads (Premier TM) are all in good condition, as are the counterhoops, all chrome work seems to be fine.

Chassis & Bowl
 There are scrapes and scuffs on the bases and the struts. One of the bowls has a repaired dent (which could have been done better), but other than that the bowls look great. A few of the struts have the rubber strip missing or taped on.

Mechanism
 These simple, and reliable mechanisms by adams need little attention, however someone has adjusted the rod lengths incorrectly which has reduced the range, and the pedal balance.

Specific Areas of Concern



The covers, although serviceable are showing signs of wear. Some of the seams are becoming un-stitched, and one has a tear in the top.



The painted mdf discs are ok, although the tie straps have mainly broken



Missing strut bumper rubber strips, those that are taped have broken the rubber pegs that hold them in place. The black circle outlines the bowl dint.

