


# Mallet Instrument Condition Report

Instrument: Xylophone  
Make: Viscount  
Model:



## Notes

The notes need to be tuned, and there are some scratches on the low end notes. There are also marks on the naturals which I think are the dyes in the felt penetrating the varnish on the notes over many years. I did however clean the low F which minimised the problem

## Frame

The frame is in good condition, although the vinyl covering is beginning to peel, but this can be glued back easily.

## Resonators

There are some scratches which have been touched in with gold paint

## Specific Areas of Concern



ERROR: undefined  
OFFENDING COMMAND: '~

STACK: