


Mallet Instrument Condition Report

Instrument: Vibraphone

Make: **Ajax**

Model:

In general this instrument is in top condition. When making the frame there were some issues over the hole drilling in the notes, not being perfect, but these instruments were hand made. In practice this means that thinner note cord than normal needs to be used to prevent the cord damping the notes on the inside of the hole. The other possibly negative is that the motor is original and therefore old - it is however working fine.



Notes

There is some pitting on the note faces to be expected on a vintage instrument.

Frame

The frame is new.

Resonators

There are some minor scratches on the resonators, and the fan shafts would be better if they were made of steel.

Specific Areas of Concern

